



• 1/64.....0.015625	• 33/64.....0.515625	•
• 1/32.....0.03125	• 17/32.....0.53125	•
• 3/64.....0.046875	• 35/64.....0.546875	•
• 1/16..... 0.0625	• 9/16..... 0.5625	•
• 5/64.....0.078125	• 37/64.....0.578125	•
• 3/32.....0.09375	• 19/32.....0.59375	•
• 7/64.....0.109375	• 39/64.....0.609375	•
• 1/8..... 0.125	• 5/8..... 0.625	•
• 9/64.....0.140625	• 41/64.....0.640625	•
• 5/32.....0.15625	• 21/32.....0.65625	•
• 11/64.....0.171875	• 43/64.....0.671875	•
• 3/16..... 0.1875	• 11/16..... 0.6875	•
• 13/64.....0.203125	• 45/64.....0.703125	•
• 7/32.....0.21875	• 23/32.....0.71875	•
• 15/64.....0.234375	• 47/64.....0.734375	•
• 1/4 0.25	• 3/4..... 0.75	•
• 17/64.....0.265625	• 49/64.....0.765625	•
• 9/32.....0.28125	• 25/32.....0.78125	•
• 19/64.....0.296875	• 51/64.....0.796875	•
• 5/16..... 0.3125	• 13/16..... 0.8125	•
• 21/64.....0.328125	• 53/64.....0.828125	•
• 11/32.....0.34375	• 27/32.....0.84375	•
• 23/64.....0.359375	• 55/64.....0.859375	•
• 3/8 0.375	• 7/8..... 0.875	•
• 25/64.....0.390625	• 57/64.....0.890625	•
• 13/32.....0.40625	• 29/32.....0.90625	•
• 27/64.....0.421875	• 59/64.....0.921875	•
• 7/16..... 0.4375	• 15/16..... 0.9375	•
• 29/64.....0.453125	• 61/64.....0.953125	•
• 15/32.....0.46875	• 31/32.....0.96875	•
• 31/64.....0.484375	• 63/64.....0.984375	•
• 1/2..... 0.50	• 1..... 1.00	•

